






BARI



40min




PH3 PZ2






13


1 → 5




6 → 10




I




II



III




IV



Ax2


Bx2

Cx1



H=20 mm

Dx1



H=25 mm


Ex3




5x40



Fx4




Gx4



6x20




Hx4



6x30




Ix2



8x60

13


Jx2



8x100

13


Kx4



Ø10

1

Cx1



H=20 mm

Dx1



H=25 mm

Ex3




5x40




PZ2


I




II



III




IV



C


E

E



E


D




2



3



4



5

Fx2



Hx4



6x30




Jx2




8x100

Kx2




Ø10




6

Cx1



H=20 mm

Dx1



H=25 mm







Ex3




5x40



PZ2




7




8

Fx2



Gx4


6x20



PH3


Ix2

8x60




Kx2

Ø10




II



I





9



10



11



12

