







GRENADA U-FORM




30min




PH3




I




II



III



Ax12




H=170 mm

Bx2



H=130-230 mm

Cx36



M6x30



PH3


Dx1

A



29V 1,5A

B



29V 2A

Ex1



4000 mm


Fx36



Ø 6 mm


1

Ax4



H=170 mm


Cx12





M6x30



Fx12




Ø 6 mm




2

Ax4




H=170 mm

Bx1



H=130-230 mm


Cx12






M6x30



Fx12




Ø 6 mm




3

Ax4




H=170 mm

Bx1



H=130-230 mm


Cx12






M6x30




Fx12




Ø 6 mm



4



5



6

